

Please change the Attorney Docket No. from "00CON107P" to --01CON314P--.

In the Drawings:

A substitute page for FIG. 4 is being submitted to correct a scrivener error. The reference number "460" to the communication channel has been replaced with --490--. Also submitted herewith is a separate page showing the proposed correction in red for approval by the Examiner.

O P E
AUG 15 2002
PATENT & TRADEMARK OFFICE 6015




Figure 4

(PROPOSED CHANGES)

O I P E
AUG 15 2002
U.S. PATENT & TRADEMARK OFFICE 601105




Figure 4

(SUBSTITUTE PAGE)